

FIG. 2




FIG. 3




FIG. 4




FIG. 5









FIG. 6














FIG. 10A

Internet					
ADDRE	SS htt	p://copia.co	om/		
(1) (1)	× (⊗	?			
FIRMWARE REWRITE					
	•	Prog 1	0	Prog 3	_ e1
	Ó	Prog 2	0	Prog 4	
k1~[EXECU	ΤE	FILE NA	ME c1. bin	-e2

FIG. 10B





FIG. 10C


Internet	
ADDRESS http://copia.com/	
	•
	•
FIRMWARE REWRITING IS COMPLETED.	∋4

c1. bin



FILE NAME

FIG. 11B



Prog 3

Prog 4

EXECUTE

- k1

FIG. 11C

FIRMWARE REWRITING IS COMPLETED. 64

FIG. 12




FIG. 13




FIG. 14




FIG. 15




FIG. 16A




FIG. 16B

	CREATE RETURN MAIL
	Subject : Re; i sw To : abc@A. co. jp From : def@A. co. jp (56AF90012)
h3~	Command uncompleted
h4 ~	Time error
	— [Get prog1, name = "CopierProg1. bin"] — [Command until 200209171252]




FIG. 18




FIG. 19A

TEST RESULTS TEST DATA CAN NOT BE RECEIVED. — m1 ERROR CODE [404] — m2

FIG. 19B

TES	ידי	$\supset \sqsubset$	CI.	II -	rc
15	۱ I	٦г.	ור	,,	

ANY COMMUNICATION ERROR IS NOT DETECTED, AND TEST DATA ARE NORMALLY RECEIVED.

CURRENT COMMUNICATION SPEED IS 100 KBPS. ESTIMATE TIME PERIODS FOR DATA RECEPTION AT THIS COMMUNICATION SPEED ARE AS FOLLOWS.

DATA SIZE	ESTIMATE TIME
1 M byte	~ 1 min. 20 sec.
5 M bytes	6 min. 40 sec.
10 M bytes	13 min. 20 sec.